




Flat Surface Damage Detection System (FSDDS)


**Dr. Martha Williams, Mark Lewis, Dr. Tracy Gibson and Dr. John Lane
Dr. Pedro Medelius, Sarah Snyder, Dan Ciarlariello and Steve Parks, KSC
Danny Carrejo and Dr. Kristina Rojdev, JSC**

Background


- KSC has been working in self healing and damage detection technologies for more than 10 years. Knowledge leveraged from the development of wiring damage detection systems.
- KSC IRTD FY11 funded project for development of hardware and software; used internal ink-jet printing technology for printing conductive traces
- Successfully demonstrated as a stand alone technology during 2011 D-RATS under IRTD.
- AES funded software modification allowed for communication with HDU avionics crew display which was demonstrated remotely (KSC to JSC) during 2012 integration testing.
- Integrated FSDDS system and stand alone multi-panel systems (AES funded) were demonstrated remotely and at JSC, Mission Operations Test using Space Network Research Federation (SNRF) network in 2012.
- FY13, FSDDS multi-panel integration with JSC and SNRF network
- Technology can allow for integration with other complementary damage detection systems
- Full patent application filed in 2012

DSH Technology & Innovations

Flat Surface Damage Detection System (FSDDS)




FSDDS sensory panels system at MOT 2012



FSDDS data on crew display during remote integration testing 2012

- **Flat Surface Damage Detection:** The Flat Surface Damage Detection system (FSDDS) is a sensory system that is capable of detecting impact damages to surfaces utilizing a novel sensor system. This system will provide the ability to monitor the integrity of an inflatable habitat during in situ system health monitoring.
- The system consists of three main custom designed subsystems: the multi-layer sensing panel, the embedded monitoring system, and the graphical user interface (GUI).
- The GUI LABVIEW software uses a custom developed damage detection algorithm to determine the damage location based on the sequence of broken sensing lines. It estimates the damage size, the maximum depth, and plots the damage location on a graph.
- Successfully demonstrated as a stand alone technology during 2011 D-RATS.
- Software modification also allowed for communication with HDU avionics crew display which was demonstrated remotely (KSC to JSC) during 2012 integration testing.
- Integrated FSDDS system and stand alone multi-panel systems were demonstrated remotely and at JSC, Mission Operations Test using Space Network Research Federation (SNRF) network in 2012.
- FY13, FSDDS multi-panel integration with JSC and SNRF network
- Technology can allow for integration with other complementary damage detection systems

Raw damage data is transmitted serially and converted to Ethernet utilizing a Power over Ethernet Black Box. Each POE Blackbox has a unique IP address and Bluetooth device that is paired with a Bluetooth device on a unique detection panel, allowing monitoring of specific detection panels. The integrated panel (Panel #1) was monitored using an iPad running the crew display application. The stand-alone panels (Panels #2 and #3) were monitored using a laptop running the GUI in the control center.




Block Diagram Pictorial Representation of the Communication Layout of the FSDDS Stand-Alone and Multi-panel Systems for FY12

DSH Technology & Innovations

Flat Surface Damage Detection System (FSDDS) FY12-F13 Status




FSDDS sensory panels system at MOT 2012



FSDDS data on crew display during remote integration testing 2012


- **Flat Surface Damage Detection:** The Flat Surface Damage Detection system (FSDDS) is a sensory system that is capable of detecting impact damages to surfaces utilizing a novel sensor system. This system will provide the ability to monitor the integrity of an inflatable habitat during in situ system health monitoring.
- The system consists of three main custom designed subsystems: the multi-layer sensing panel, the embedded monitoring system, and the graphical user interface (GUI).
- The GUI LABVIEW software uses a custom developed damage detection algorithm to determine the damage location based on the sequence of broken sensing lines. It estimates the damage size, the maximum depth, and plots the damage location on a graph.
- Integrated FSDDS system and stand alone multi-panel systems were demonstrated remotely and at JSC, Mission Operations Test using Space Network Research Federation (SNRF) network in 2012 (pictures left).

Raw damage data is transmitted serially and converted to Ethernet utilizing a Power over Ethernet Black Box. Each POE Blackbox has a unique IP address and Bluetooth device that is paired with a Bluetooth device on a unique detection panel, allowing monitoring of specific detection panels. The integrated panel (Panel #1) was monitored using an iPad running the crew display application. The stand-alone panels (Panels #2 and #3) were monitored using a laptop running the GUI in the control center.



Block Diagram Pictorial Representation of the Communication Layout of the FSDDS Stand-Alone and Multi-panel Systems for FY12

FSDDS DSH software interfaces




FSDDS Operations Summary

- The operation of the damage detection system is based on the use of parallel **conductive traces placed on a firm or flexible surface**.
- Several detection layers can be implemented, **where alternate layers are arranged in an orthogonal direction with respect to adjacent layers**. The orthogonal arrangement allows for pinpointing the exact location of the damage to the surface under test. **Multiple detection layers allow for the calculation of the depth of the damage** to the surface under test.
- **Minimizes the use of active electronic components** to reduce the risk of incorrect operation due to radiation factors. The **FSDSS circuit uses only two active components: a microcontroller, and a serial port bidirectional driver/receiver**. Wireless communication.
- **Microcontroller is used to inject and monitor test signals to determine the integrity of the sensing lines**
- **The data is transmitted wirelessly to a central commuting system**
- **A GUI monitors and controls the system.**

FSDDS Detection Panel Design

Damage Detection Test Panel Assembly



Legend:



Conductive Traces




Adhesive




Fabric



Damage Detection Panel Fabrication




Insulation side of
laboratory (left)
and commercially
(right) printed
circuitry





Fabric side of
laboratory printed and
assembled multi-
layered system (left)
and commercially
(right) printed circuitry
and laboratory
assembled multi-
layered system (right)



Close up of
laboratory ink-jet
printed
circuitry(left)








Three Dimensional Damage Detection

Configuration Display



Start Monitoring

Stop Monitoring

Monitoring (T)

Status Data Received (T)

Display Defect Lines (T)

Length (Inches)

Damage Color Legend

Top Layer

2nd Layer

3rd Layer

Bottom Layer

Defects - Represented by DashDotDot Line Type
Unresolved Damage - Represented by Solid Line Type

1 Scanning Rate (Sec)

446 Total Available Lines

0 Current Damaged Lines

Detected Damage Attributes

Damage ID 3 Total Lines Broken 6

Damage Zones

0 YES X-Y Coordinates Accurate (T)

X-Y Coordinates

X

5.08

Y

5.2

Defect Lines Found Near Zone

0

465

Defects Found Near Zone

4

Estimated Damage Lines Width

3

Estimated Damage Lines Length

3

Damage Depth Layer

2

Estimated Area (Sq. Inches)

0.0144

Estimated Width (Inches)

0.12

Estimated Length (Inches)

0.12

Damaged Lines / Zone

0

463

Broken Lines / Zone

6

Coordinate Depth Layer

0


Blue


3 Current Max Damage ID


226 Total Broken Lines

QUIT

FSDDS DSH test configuration







FSDDS Display Screen of Simultaneous (KSC and JSC) and Remote monitoring of multiple detection panels

FSDDS Front Panel V3.0.vi

File Edit View Project Operate Tools Window Help

FSDDS COMMAND CONSOLE

READ ALL PANELS BASELINE DATA ☒ ALL Data Received (T)

ERASE SELECTED PANEL MEMORY ☒ ALL Erase Baseline CMDs Received (T)

3
4
5 Installed Panel ID Numbers

CREATE DAMAGE RECORDS FILE

LOAD DAMAGE RECORDS FILE ☒ Mask Enabled (Checked)

SCRIPT CMD EXECUTION
START_MONITOR 4 Sequence Counter

Start Monitoring Stop Monitoring ☒ Monitoring (T) ☒ Sampled (T)

Read String Array (ASCII)

Read String Array (Hex)

RECONFIGURE SYSTEM

CLEAR DISPLAY

☐ Display Defect Lines (T)
☐ Edit FSDDS Configuration (T)

FSDDS Configuration Parameters

Mode **AUTOMATIC**

Script File Bypass ☐ Enabled

3 Panel Qty

168 Detection Lines/Layer

0.04 Resolution (Inches)

10 Scanning Rate (Sec)

2101 Port

Ethernet-Serial Port IP Addresses

10.10.5.153
10.10.26.2
10.10.26.3

☒ TCP Comm Good (T)

Network Streams HDU DATA
☒ Enabled (Checked)

☒ Network Streams Comm Good (T)

HDU writer url
//localhost/FSDDS_Front_Panel_V3.0/reduced_data_writer

HDU reader url
//10.10.5.22:FSDDS_HOST/REDUCED_DATA_READER

Panel Baseline Statistics From Flash Memory

3 Panel ID

30 Total # Baselined Damaged Lines

2 Baselined Damage ID Max

14 Total # of Defect Lines

0 Baselined Damage Lines (0-671)

0 Baselined Damage IDs

FSDDS STATUS CONSOLE

Panel Masked Baseline Damage Statistics

10 Total # Baselined Damaged Lines After Mask

0 Baselined Damage Lines After Mask (0-671)

1 Baselined Damage IDs After Mask

SYSTEM ERRORS

status code


0

000000

Damage Number Mapping

Hardware Panel	Test Panel
Layer 1: 0-167	Layer 1: 336-503
Layer 2: 168-335	Layer 2: 504-671
Layer 3: 336-503	Layer 3: 0-167
Layer 4: 504-671	Layer 4: 168-335

FSDDS Labview Display of Multi-Panel Systems



Matrix Math Software upgrade being considered

Back up slides



Damage Detection and Self-Repair in Inflatable/Deployable Structures

NASA's Jet Propulsion Laboratory
Sunday, March 01 2009

Integrated sensors and self-repairing materials provide structural health management.

Inflatable/deployable structures are under consideration for applications as varied as expansion modules for the International Space Station to destinations for space tourism to habitats for the lunar surface. Monitoring and maintaining the integrity of the physical structure is critical, particularly since these structures rely on non-traditional engineering materials such as fabrics, foams, and elastomeric polymers to provide the primary protection for the human crew. The closely related prior concept of monitoring structural integrity by use of built-in or permanently attached sensors has been applied to structures made of such standard engineering materials as metals, alloys, and rigid composites. To effect monitoring of flexible structures comprised mainly of soft goods, however, it will be necessary to solve a different set of problems — especially those of integrating power and data-transfer cabling that can withstand, and not unduly interfere with, stowage and subsequent deployment of the structures. By incorporating capabilities for self-repair along with capabilities for structural health monitoring, successful implementation of these technologies would be a significant step toward semi-autonomous structures, which need little human intervention to maintain. This would not only increase the safety of these structures, but also reduce the inspection and maintenance costs associated with more conventional structures.

A series of proof-of-concept technology sensing and self-repair technologies have recently been developed and tested individually, for future integration into a full health management system for inflatable/deployable structures. With further development, these technologies could be applied individually or as part of an entire system, depending on the particular architecture of the structure or on the specific mission needs. The technologies include:

- Arrays of thin-film capacitive or inductive sensors, made of a flexible circuit material that can be integrated into an inflatable/deployable structure for use in detecting the location and extent of damage. Damage manifests itself as changes in inductance or capacitance in elements of the sensor array.
- Strain gauges made from thin films of amorphous silicon for monitoring the integrity of thin, flexible structures. To reduce the amount of wiring required, thin-film transistors are used to construct an addressable, matrixed array of sensors allowing selection and readout of specific sensors in the array.
- Wireless sensors and passive (no-power) radio-frequency identification sensor tags to provide additional sensing capabilities such as strain sensing, temperature sensing, and impact or leak detection, without the need for data and power cables.
- Self-repairing elastomeric materials (such as those used to construct the bladder of a habitat), which incorporate microcapsules filled with a monomer resin and a small amount of a polymerization catalyst. Upon damage to the material, some of the capsules burst and release the monomer, becoming polymerized after making contact with the embedded catalyst and thus effecting repair of the damage.
- Sensory and self-repair features will eventually be combined into the structure to effect a unified structural health maintenance system. Sensors will alert humans to initial damage and will monitor the self-repair process, to indicate whether there is a need for human intervention for inspection and/or repair.

This work was done by Erik Brandon of Caltech, George Studor of NASA Johnson Space Center, David Banks and Mark Curry of Boeing Phantom Works, Robert Broccato of Sandia National Laboratories, Tom Jackson of Penn State University, Kevin Champaigne of Invocon, Stan Woodard of NASA Langley Research Center, and Nancy Sottos of the University of Illinois at Urbana-Champaign for NASA's Jet Propulsion Laboratory. For more information, contact iaoffice@jpl.nasa.gov . NPO-44519